



Update-Description

inLab Splint 19.1

This document describes changes and improvements compared to previous version inLab Splint 19.0

September 2019

Following topics have been corrected

- Problem solved with issues on custom tray handle geometry breaking through on the inside
- Problem solved with geometry issues while using the form tool

Quality improvement and stability

Dentsply Sirona continuously improves the quality of its products. As part of this release, several improvements have been made and known software bugs have been fixed. We always recommend using the latest software version.